







ASBESTOS REGISTER PRINTING INSTRUCTIONS

<p>Step 1</p>	<p>Go to www.housing.wa.gov.au > go to bottom of the page to locate/select Asbestos Register</p>	
<p>Step 2</p>	<p>Login using current Contractor Code and Password.</p> <p>Details of current code/passwords can be requested from acmhousing@housing.wa.gov.au</p>	
<p>Step 3</p>	<p>Agreement Read and acknowledge the Agreement, and select Next</p>	
<p>Step 4</p>	<p>Enter the Property ID, and select Search; then select YES to access the Asbestos Register.</p>	



Step 5 View Asbestos Register, then **select PDF Preview** to print

Inspection List

Property ID:

Address:

Last Inspection Date: Inspector Name:

Dwelling Component	Room Element	Type	Qty	Size	UOM	Asbestos Type	Condition	Probability	Risk Rating	Detection Code	Comment
Laundry	Ceiling	Asbestos containing material	1.00	7.50	m2	BONDED	Fair	Medium	5	SUSPECTED	inspected 10/02/201 condition - change CI Inspected cgeogc1 u

Step 6 You will see a popup box asking if you wish to open or save a .PDF form. **Select Save** then **Open** if you only wish to print; otherwise select **Save as**.

What do you want to do with PropertyID_...pdf?
From: asbestosregister.housing.wa.gov.au

Step 7 **Select Print Icon** and print as usual. The Asbestos Register can be saved as a document from this screen as well.

Document

Government of **Western Australia**
Department of **Communities** 19-09-2017

Asbestos Register

Property:
Property Name:

Dwelling Component	Room Element	Material Type	Asbestos Type	Condition	Probability	Detection Code	Risk Rating	Location	Comment
External / Others	Eaves	Lined	BONDED	Good	Low	SUSPECTED	Very Low	EXTERNAL/OTHERS- EXTERNAL/OTHERS 1- Eaves	<input type="text"/>
External / Others	Front External Walls	Asbestos containing material	BONDED	Good	Low	SUSPECTED	Very Low	wall cladding	<input type="text"/>
External / Others	Rear External Walls	Asbestos containing material	BONDED	Good	Low	SUSPECTED	Very Low	rear walls	<input type="text"/>
External / Others	Left External Walls	Asbestos containing material	BONDED	Good	Low	SUSPECTED	Very Low	left wall	<input type="text"/>